



Fig. Z

Service-affecting Line-level Alarms –
Equipment
Unit Fail
Improper Removal
Line Level Alarms
Service-affecting Line-level Alarms - Facility
Line AIS
B2 Signal Degrade
LOF
LOS
Optical Output Failure
RFI
Span Switch Fail

Fig. 3







